



Rudi Kovacko & Associates Inc.
1197 Fewster Drive, Unit A
Mississauga, Ontario L4W 1A2
Telephone: (905) 238-0308
Fax: (905) 238-6327
E-Mail: info@rudikovacko.com


We Rebuild:

Lightnin Prochem Chemineer Hayward Gordon Beloit GL&V Philadelphia Mixers Black Clawson Sulzer/Ahlstrom

Our diverse knowledge of rotating equipment and manufacturing methods, coupled with our intimacy with most brands of mixing equipment, provides us with valuable insight into the failure mechanism. This understanding enables us to supply a superior, more reliable rebuild installation.



To excel in this competitive rebuild market, a company must first fully understand “why rotating equipment fails”. In some cases, the misapplication of a mixer installation will cause premature failure or damage to a mixer rotating assembly. In other cases, improper installation or fatigue can be the culprit. Incompatible metallurgy, undersized/oversized units, excessive vibration and poor maintenance are just a few more examples of why mixers fail.



Rebuilding a mixer requires more than having a top notch machine shop. Understanding the root cause of mechanical failure is instrumental in supplying a successful and reliable rebuild installation.